



**FRESE HW PER ANGOLI ARROTONDATI Z=2**

ART. E342 - G342



S Ø 12	S Ø 12,7 (1/2")	D	B	R	L
E342.286.R	G342.286.R	28,6	13	10	73



Z050.104.N





Z058.003.N



Z051.005.R

**FRESE HW PER BASSOFONDO**



ART. E350 - G350



S Ø 12	S Ø 12,7 (1/2")	D	B	L	Z	α
E350.520.R	G350.520.R	52	6,5	83	6	0,5x45°
E350.521.R	G350.521.R	52	6,5	83	6	0°

**FRESE HW PER DECORI Z=2**



ART. E360



S Ø 12	D	B	R	L
E360.246.R	24,6	16	2	60

**FRESE HW PER DECORI Z=2**

ART. E361






S Ø 12	D	B	R	L
E361.127.R	12,7	13	3,2	51
E361.160.R	16	13	3,2	51
E361.190.R*	19	13	3,2	51
E361.254.R*	25,4	13	3,2	51

\* Ad esaurimento scorte

**FRESE HW PER BORDI SAGOMATI Z=2**

ART. E362



Con cuscinetto conico

S Ø 12	D	D1	B	R	L	α
E362.420.R*	42	22	33	6,4	84	10°

\* Ad esaurimento scorte



Z050.102.N





Z053.002.N



Z051.004.R

**FRESE HW PER BORDI DECORATI Z=2**

ART. E363



S Ø 12	D	B	B1	R	L	α
E363.350.R*	35	36,5	12-13	3,2	89	45°

\* Ad esaurimento scorte



Z050.011.N



Z054.003.N



Z051.004.R